L	Hits	Search Text	DB	Time stamp
Number 1	38	drop adj out adj box	USPAT;	2003/05/14
			US-PGPUB; EPO; JPO;	09:45
2	3	post adj combustion adj material	DERWENT USPAT;	2003/05/14
-		post day compassion day material	US-PGPUB;	09:48
			EPO; JPO; DERWENT	
3	1	kimmel-scott-b\$.in.	USPAT; US-PGPUB;	2003/05/14
			EPO; JPO;	
4	3	mcclintock-willard-k\$.in.	DERWENT USPAT;	2003/05/14
			US-PGPUB; EPO; JPO;	09:54
_		75 /220 1 -	DERWENT	2003/05/14
5	66	75/320.ccls.	USPAT; US-PGPUB;	09:57
			EPO; JPO; DERWENT	
6	122734	coal	USPAT; US-PGPUB;	2003/05/14
			EPO; JPO;	05.50
7	239803	recycl\$	DERWENT USPAT;	2003/05/14
		-	US-PGPUB; EPO; JPO;	09:58
	_		DERWENT	0000/05/14
8	5	75/320.ccls. and coal and recycl\$	USPAT; US-PGPUB;	2003/05/14 10:03
		·	EPO; JPO; DERWENT	
9	314	75/961.ccls.	USPAT;	2003/05/14
			US-PGPUB; EPO; JPO;	10:10
10	588353	 drying	DERWENT USPAT;	2003/05/14
			US-PGPUB; EPO; JPO;	10:11
			DERWENT	
11	763950	dry	USPAT; US-PGPUB;	2003/05/14
			EPO; JPO;	
12	660157	dried	DERWENT USPAT;	2003/05/14
			US-PGPUB; EPO; JPO;	10:11
13	1326592	drying or dry or dried	DERWENT USPAT;	2003/05/14
			US-PGPUB;	10:12
			EPO; JPO; DERWENT	
14	131	75/961.ccls. and (drying or dry or dried)	USPAT; US-PGPUB;	2003/05/14
			EPO; JPO; DERWENT	
15	8	electric adj arc adj flue adj dust	USPAT;	2003/05/14
			US-PGPUB; EPO; JPO;	10:13
16	1098	flue adj dust	DERWENT USPAT;	2003/05/14
	1000		US-PGPUB;	10:14
			EPO; JPO; DERWENT	
17	389	eaf	USPAT; US-PGPUB;	2003/05/14 10:14
			EPO; JPO;	
L			DERWENT	

			,	•	
Г18		33	75/961.ccls. and eaf	USPAT;	2003/05/14
1 - 0			70, 302.002.0	US-PGPUB;	10:15
	1			EPO; JPO;	
				DERWENT	
19		26	(75/961.ccls. and (drying or dry or	USPAT;	2003/05/14
1		20	dried)) and eaf	US-PGPUB;	10:28
			arrea,, and our	EPO; JPO;	
				DERWENT	
20	İ	0	drop adj out adj box adj slag	USPAT;	2003/05/14
20		· ·	alop aaj oad aaj zon aaj zeng	US-PGPUB;	10:31
				EPO; JPO;	
				DERWENT	
21	1	1	drop adj out adj box adj material	USPAT;	2003/05/14
41		-	diop adjout adjour adjoudettat	US-PGPUB;	10:36
	1			EPO; JPO;	
				DERWENT	
22	1	1015	dob	USPAT;	2003/05/14
22	1	1015	uob	US-PGPUB;	10:33
				EPO; JPO;	
				DERWENT	
23		0	(electric adj arc adj flue adj dust) and	USPAT;	2003/05/14
23	1	· ·	dob	US-PGPUB;	10:33
	1		l dob	EPO; JPO;	20100
	1			DERWENT	
24		0	eaf and dob	USPAT;	2003/05/14
~ ~	ŀ	ŭ		US-PGPUB;	10:34
	1			EPO; JPO;	
Ì	1			DERWENT	
25	1	0	(flue adj dust) and dob	USPAT;	2003/05/14
1 - 0		· ·	(22.00 0.0) 0.000	US-PGPUB;	10:34
i	į			EPO; JPO;	
	İ			DERWENT	
26	1	2945	steelmaking	USPAT;	2003/05/14
- "	i			US-PGPUB;	10:35
				EPO; JPO;	
				DERWENT	
27		0	steelmaking and dob	USPAT;	2003/05/14
- '		•		US-PGPUB;	10:35
				EPO; JPO;	
	i			DERWENT	
28		38	drop adj out adj box	USPAT;	2003/05/14
				US-PGPUB;	11:33
				EPO; JPO;	
				DERWENT	1